

Importer's name: Finder plc

Importer's address: Opal Way
 Stone Business Park
 Stone
 Staffordshire
 ST15 0SS
 UK

Declares under sole responsibility that the product as originally delivered:

Product: 94 Series: Sockets for 55/85 Series Relays

Manufacturer's name: Finder SpA

Manufacturer's address: Via Drubiaglio 14
 10040
 Almese (TO)
 Italy

Complies with the following statutory requirements and carries the UKCA mark accordingly	By conforming to the following designated standards.
Electrical Equipment (Safety) Regulations 2016 No.1101 [as amended]	BS EN 60664-1:2007
Restriction of the Use of Certain Hazardous Substances in Electrical and Electronic Equipment Regulations 2012 No.3032 [as amended]	BS EN IEC 63000:2018

Signed for and on behalf of:	Finder plc
Issued at:	Stone, Staffordshire
Date:	21 st June 2021
Name:	Jonathan Stanford
Function:	Managing Director
Signature:	