



D

C

B

A

213

40

4 positions in order to set the tool's stroke (see detail)

51

Detail

8,2

15,3

closed tool position
opened tool position

X=stroke

- X1=4.6
- X2=4.2
- X3=3.8
- X4=3.5

62

cable max ϕ : 5,7 mm

					Dat.	Name		har.link®	free connector CABLE CRIMP TOOL	Maßstab/ Scale 3/4	
					Detail.	05-JAN-01					JB
					Insp.						
					Stand.						
27966	05-JAN-01	JB			HARTING EURL F-95972 Paris			TB 27 99 000 0001		Blatt/ Page 1/1	
Mod.	Dat.	Name						Sub. 27 99 000 0001.01			